

**PECFA number:** 54501-7758-91  
**BRRTS number:** 03-44-000414  
**Site Owner:** Louis Liatses, AJC Company LLC  
**Site Name:** Former Van's Bar & Grill  
**Site Address:** 1691 Hwy 8, Monico, WI

**Program contact:** Denise Nettesheim, Site Review Hydrogeologist  
**Program contact address:** 201 W. Washington Ave., P.O. Box 8044, Madison, WI 53708  
**Program contact phone:** (608) 261-7719

### **Submitted Questions and Responses**

1. Records in the SIR report other data appear to indicate that the on-site potable well was not sampled. Will this be required as part of the remedial action?

**Of course, on-site potable wells should always be sampled as part of remedial action activities.**

2. How much PECFA fund has been used for this site?

**No claims have been submitted to date. It is unknown how much has been spent in the investigation phase.**

3. Is the wetland surrounding Monico Lake identified and delineated?

**The wetland is delineated.**

4. Groundwater flow is reported to flow to north and northeast. This is our understanding that Mohr's Auto Repair, closed by the WDNR in 1996, is located north of the site. If contamination moves from Van's Bar and Grill to Mohr's Auto Repair, will COMMERCE permit to conduct investigation at a closed site?

**The fact that Mohr's is a closed site does not matter. If the groundwater plume moves to the Mohr's Auto Repair property, the plume will have to be investigated.**

5. Have the investigative wastes (soil cuttings & groundwater) from the SI been disposed? If not, how many drums of each are left on site?

**The wastes have not been disposed of. Soil cuttings are currently stockpiled on site, approximately six cubic yards of soil is present. There are two drums of waste groundwater on site.**